Fatigue−Resistant Weld Design

POOR FATIGUE RESISTANCE



Sharp toe angle
High reinforcement

GOOD FATIGUE RESISTANCE



Smooth toe blend
Low reinforcement