# Five Basic Weld Joint Types

## BUTT JOINT



*Parts aligned*
*in same plane*

## LAP JOINT



*Overlapping*
*parts*

## T-JOINT



*Parts at 90°*
*(T−shape)*

## CORNER JOINT



*Parts at 90°*
*(L−shape)*

## EDGE JOINT



*Parallel edges*
*adjacent*