Common Weld Defects

POROSITY



Gas pockets
trapped in weld

UNDERCUT



Groove melted into
base metal at toe

LACK OF FUSION



Weld metal doesn't
fuse with base

INCOMPLETE PENETRATION



Root not
fused

CRACK



Most serious
defect

SPATTER



Metal droplets
on surface