Weld Sizing: Not Too Small, Not Too Large

UNDERSIZED



Insufficient strength

✕

CORRECT



Adequate strength
Minimum distortion

⊕

OVERSIZED



Excessive heat
Distortion

✕