
Tolerance vs. Machining Cost
Relative Cost (Baseline = 1)
30
20
10
0
uper Finish
Hone
Lap
Fine Grind
Grind
Finish Turn
Rough Turn
0.01
0.03
0.10
0.30
Tolerance (mm) − Log Scale