
Never converges −> singularity, ignore
Converges −> trust it
Peak von Mises stress (MPa)
300
200
0
50000
100000
150000
Degrees of freedom (mesh refinement)
Filleted
Sharp corner