



# Common Gear Failure Modes

## Bending Fatigue




Crack at root fillet  
from cyclic loading

## Surface Pitting



Surface fatigue  
from contact stress

## Adhesive Wear



Material loss from  
insufficient lubrication