

Joining Process Selection Matrix

Scores: 1 (Poor) to 5 (Excellent)

	Permanent	High Temp	Dissimilar Materials	Thin Sheet	Removable	Low Cost
Rivets	3	4	5	4	3	4
Bolts	1	1	1	1	5	2
Adhesive	3	4	5	5	2	4
Soldering	2	3	3	5	4	3
Brazing	5	4	1	1	5	4
Welding	5	4	3	4	2	5