



Supplementary Welding Symbols

Weld All
Around



Field Weld
(on site)



Flush
Contour



Convex
Contour



Concave
Contour



Backing
Bar

