


Weld Sizing: Not Too Small, Not Too Large


UNDERSIZED



Insufficient
strength




CORRECT



Adequate strength
Minimum distortion



OVERSIZED



Excessive heat
Distortion

