

Overturning Stability Check — Precision Inspection Fixture

Tall, high-CG fixture: lateral disturbance vs. restoring moment about the leading edge

