


PV Limit Curves for Common Bushing Materials

Operating point must fall BELOW the curve for the selected material



Material

— Bronze (PV=50,000)

— Nylon (PV=5,000)

— PTFE-Lined (PV=15,000)

— Sintered Bronze (PV=35,000)