
Critical Speed vs. Unsupported Span
Critical speed (rpm)
20000
15000
10000
5000
0
1.0
1.5
2.0
Span, L (m)
Operating point
(L = 1.35 m)
Required speed (2400 rpm)
End condition
Fixed−Fixed
Fixed−Free
Fixed−Supported (this axis)