

Groove Weld Preparation Dimensions

Typical Values:

Groove Angle: $60^{\circ} - 90^{\circ}$

Root Opening: 0 – 3 mm

Root Face: 1 – 3 mm

