



Five Basic Weld Joint Types

BUTT JOINT




*Parts aligned
in same plane*

LAP JOINT




*Overlapping
parts*



*Parts at 90°
(T-shape)*

CORNER JOINT



*Parts at 90°
(L-shape)*

EDGE JOINT



*Parallel edges
adjacent*