




Common Weld Defects




Gas pockets
trapped in weld




Groove melted into
base metal at toe




Weld metal doesn't
fuse with base



Root not
fused



Most serious
defect



Metal droplets
on surface