


Powder Metallurgy Process Flow


1. POWDER PRODUCTION



*Atomization,
reduction, or
electrolysis*




2. BLENDING



*Mix with lubricants
and additives*




3. COMPACTION



*Press at
400–700 MPa*



4. SINTERING



*Heat to 70–90%
of melting point*