Overturning Stability Check — Precision Inspection Fixture

Tall, high−CG fixture: lateral disturbance vs. restoring moment about the leading edge