Straightness Control Example

Feature must remain within 0.3 mm total straightness tolerance

type ▬ Perfect (0.0 mm) ▬ With 0.3 mm Tolerance