

The Six Big Losses: Targets for TPM Improvement

AVAILABILITY LOSSES

1

Equipment Failure

2

Setup & Adjustment

PERFORMANCE LOSSES

3

Idling & Minor Stops

4

Reduced Speed

QUALITY LOSSES

5

Process Defects

6

Startup Rejects