


Two-Hand Control: Both Hands Must Be on Buttons

Ensures operator's hands are away from the danger zone during machine cycle

Both buttons
pressed within
0.5 seconds

Anti-tie-down
prevents
bypassing



PRESS