OEE: The TPM Scorecard

OEE = Availability × Performance × Quality

AVAILABILITY

Run Time
÷
Planned Production Time

PERFORMANCE

Ideal Cycle Time × Total Count
÷
Run Time

QUALITY

Good Count
÷
Total Count

**Downtime
Losses**

**Speed
Losses**

**Quality
Losses**