Work Cycle Distribution by Automation Level

Legend: Operator, Machine

Manual — 100% Operator Control

Semi-Auto — Load/Unload | Auto Cycle

Fully Auto — Automated Operation (Unattended)

Percentage of Cycle Time

0   25   50   75   100