The P–F Curve

Different sensor types detect failure at different positions on the