
Common Sources of Measurement Error by Category
Classified by primary impact on measurement system
Part
Method
Equipment
Environment
Appraiser
Surface finish
Part flexibility
Unclear procedures
Inconsistent setup
Wrong reference point
Poor resolution
Worn components
Fixture issues
Calibration drift
Contamination/cleanliness
Temperature effects
Training gaps
Technique variation
Fatigue/attention
0
1
2
3
4
Number of Error Sources
Impact
Bias
Repeatability
Reproducibility
Bias & Repeatability
Repeatability & Reproducibility
Resolution/ndc