
Typical Loss Distribution (40% Total Losses)
Manufacturing example − varies by industry and equipment
Time Loss (%)
0
5
10
12%
10%
8%
5%
3%
2%
Setup/Adjustment
Equipment Failure
Minor Stops
Reduced Speed
Process Defects
Startup Rejects
category
Availability
Performance
Quality