Out−of−Control Response Procedure



. Circle the point
. Note the time
. Quarantine product

. Check 5 Ms
. Review recent changes
. Ask operators

. Fix the problem
. Verify correction
. Restart process

. Update log
. File in PFMEA
. Share lessons