
Typical Loss Distribution (40% Total Losses)
Manufacturing example − varies by industry and equipment
Time Loss (%)
12.5
10.0
7.5
5.0
2.5
0.0
10%
8%
5%
3%
2%
Setup/Adjustment
Equipment Failure
Minor Stops
Reduced Speed
Process Defects
Startup Rejects
category
Availability
Performance
Quality