
Pareto Chart: Manufacturing Defects by Type
Focus on Surface Scratch and Dimensional Error to address 58% of all defects
Defect Count
Cumulative %
Defect Type
80% line
145
98
67
34
28
21
15
12
35%
58%
74%
82%
89%
94%
97%
100%
Surface Scratch
Dimensional Error
Burrs
Missing Feature
Wrong Material
Contamination
Color Mismatch
Packaging Damage