

Pareto Chart: Manufacturing Defects by Type

Focus on Surface Scratch and Dimensional Error to address 58% of all defects

