


The 10-Step PFMEA Process

A systematic approach to process risk analysis



phase ■ Analyze ■ Improve ■ Plan ■ Prioritize