
Recognizing In−Control vs. Out−of−Control Conditions
In Control
Out of Control
Measured Value
56
52
48
44
0
5
10
15
20
25
Sample Number