
Where the Uncertainty Comes From
Share of the combined variance, type A (data) and type B (documents)
Repeatability (s = 0.0015)
Calibration certificate (U = 0.002, k = 2)
Temperature (+/−2 C)
Resolution (0.001 mm)
65%
29%
3%
2%
0
25
50
75
100
Share of combined variance (%)
Type
A
B