
Stratified Pareto: Causes of Surface Scratch Defects
Drilling down into the #1 defect type
52
38
28
15
8
4
Count
Cumulative %
0
10
20
30
40
50
0
25
50
75
100
Handling damage
Fixture marks
Chip scratches
Conveyor marks
Tool marks
Unknown
Scratch Cause