



Impact of Measurement System Quality on Control Charts

Same stable process measured with different gauge quality (same y-axis scale on both charts)

Good MSA (%GRR = 15%)



Poor MSA (%GRR = 93%)



Sample Number