

# Robot Coordinate Systems

Different reference frames for programming and motion

## Coordinate Types:

- Joint: J1, J2, J3, J4, J5, J6 (degrees)
- Cartesian: X, Y, Z, Rx, Ry, Rz (mm, degrees)
- Tool: Relative to end effector

