

AIAG Automotive Core Tools

Five essential tools required by IATF 16949

APQP
Advanced Product
Quality Planning
Define quality
Define quality

PPAP
Production Part
Approval Process
Control production
Control production

FMEA
Failure Mode &
Effects Analysis
Identify and mitigate
Identify and mitigate

MSA
Measurement
Systems Analysis
Improve measurement
Improve measurement

SPC
Statistical
Process Control
Identify control pro
Identify control pro