
Time Breakdown per Unit − Identifying Improvement Opportunities
MCE = Value−Added Time / Total Time = 43.75%
3.5 min
2.5 min
1.5 min
0.5 min
Time (minutes)
0
1
2
3
Value−Added (Processing)
Waiting
Moving
Inspection
Category
Necessary
Value−Added
Waste