Safety Distance: Ensuring Time to Stop

The device must be far enough that the machine stops before the person reaches the hazard

$$S = (K \times T) + C$$