

AIAG Automotive Core Tools

Five essential tools required by IATF 16949

APQP
Advanced Product
Quality Planning

Define quality

PPAP
Production Part
Approval Process

Control production

FMEA
Failure Mode & Effects Analysis

Identify and mitigate

MSA
Measurement
Systems Analysis

Improve measurement

SPC
Statistical
Process Control

Monitor and control process