

# The Same Parts Measured by Two Different Systems

Poor measurement systems lead to incorrect accept/reject decisions

