

AIAG Automotive Core Tools

Five essential tools required by IATF 16949

APQP

Advanced Product
Quality Planning

and define quality plan

PPAP

Production Part
Approval Process

onstrate production cap

FMEA

Failure Mode &
Effects Analysis

entify and mitigate risk

MSA

Measurement
Systems Analysis

sure measurement vali

SPC

Statistical
Process Control

itor and control proces