
Manufacturing Process Selection Guide
Choose processes based on volume requirements and part complexity
Part Complexity
Very High
High
Medium
Low
Simple
3D Printing
Investment Casting
CNC Machining
Injection Molding
Manual Assembly
Sand Casting
Die Casting
Thermoforming
Forging
Blow Molding
Stamping
Extrusion
Prototype (1−10)
Low (10−1K)
Medium (1K−10K)
High (10K−100K)
Mass (100K+)
Production Volume
Category
Additive
Forming
Machining
Casting
Joining
Molding