Two−Hand Control: Both Hands Must Be on Buttons

Ensures operator's hands are away from the danger zone during machine cycle