

5 Whys Analysis: Production Line Stoppage

Each 'Why?' digs deeper toward the root cause

Problem:

Production line stopped



Why #1:

The robot arm stopped moving



Why #2:

The servo motor overloaded and faulted



Why #3:

The gearbox was binding due to wear



Why #4:

The gearbox lubrication had degraded



Why #5:

The lubrication was never changed
(No PM schedule existed)