
The Seven Wastes: TIMWOOD
Ranked by typical impact on manufacturing efficiency
Typical Impact
High
Medium
Low
Excess stock
Making too much
Rework/ scrap
Idle time
Extra work
Moving materials
Unnecessary movement
I
O
D
W
O
T
M
Inventory
Overproduction
Defects
Waiting
Over−processing
Transport
Motion
Type of Waste