Robot Coordinate Systems

Different reference frames for programming and motion

Coordinate Types:

. Joint: J1, J2, J3, J4, J5, J6 (degrees)

. Cartesian: X, Y, Z, Rx, Ry, Rz (mm, degrees)

. Tool: Relative to end effector