





How Cold Rolling Elongates the Grains

Before: equiaxed grains,
full thickness



After: elongated grains,
reduced thickness



rolling direction (direction of travel)

Phase  Ferrite  Pearlite