
Hardness vs. Tempering Temperature
as−quenched
(low temper)
70
60
50
40
30
Hardness (HRC)
200
300
400
500
600
Tempering Temperature (deg C)