

AIAG Automotive Core Tools

Five essential tools required by IATF 16949

APQP
Advanced Product
Quality Planning

Define quality requirements and define controls

PPAP
Production Part
Approval Process

Verify production readiness

FMEA
Failure Mode &
Effects Analysis

Identify and mitigate risks

MSA
Measurement
Systems Analysis

Ensure measurement reliability

SPC
Statistical
Process Control

Monitor and control process variability